

Safety Information Brief



BHP Mitsubishi Alliance

BMA Hay Point Coal Terminal

Released: 18th September 2020

Heaving Lights – Red & Green

Recently there was an incident at Hay Point Coal Terminal (HPCT) where the terminal line handling Crew were placed in the line of fire, of a Line Under tension, because the Ship's crew tensioned lines while the Red (DO NOT TENSION) light was flashing. This placed the terminal line handling crew in the unacceptable position of a snap back zone, due to the vessel crew not following the terminal safety requirements and instructions.

This is a reminder to all Vessels attending HPCT to follow the **Hay Point Procedure – Port Information & Regulations for Vessels arriving (ID 000196672)**, available via your Shipping Agent and in particular the DO NOT Tension Light requirements, during line handling activities.

The safety of our team members is paramount and we need your help to ensure that everyone can complete their task safely.




Figure 4: Heaving Lights Definition

For further information, please contact Hay Point Terminal

Distributed via Hay Point Terminal Agent - Wilhelmsen

Approved by Department Manager – Darryl Sweet